

151454

Tuesday, September 27, 2016 11:53:51 AM

N900040100

Setup Start *NS1*

Stop *NS2*

Cust Item ID:

Start Date: 9/21/2016 **Start Qty:** 1.00

~~*1*~~ 7

Customer:

Required Date: 9/27/2016 **Req'd Qty:** 1.00

~~*1*~~ 2

Reference:

Approvals: Process Plan: **DAS** Date: **SEP 28 2016**
21

Tooling: _____ **Date:** _____

Run Start *NR1*

OC: 9-89

Date: _____ **SPC (Y/N):** _____ **Date:** _____

SPC (Y/N): _____ Date: _____

Stop ***NR2***

[illegible]

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY			
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong	
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions	
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance	
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect	
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing	
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved	
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing	
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish	
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread	
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence	
Past Expiry Date ☐	☐ Manufacturing Process	OTHER :				
Misidentified ☐	☐ Past Due					

Work Order ID 151454

Tuesday, September 27, 2016 11:53:51 AM

151454

Page 2

Item ID: D3690-1 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Glareshield
Start Date: 9/21/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 9/27/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
115 *115* HandThermo Hand Finishing Thermoforming	Dry Material Memo Dry Sheet as per QSI022 POLYCARBONATE Temp: <u>245 deg. F</u> Time IN: <u>5:00 PM</u> Time OUT: <u>6:00 AM</u>	0.00 0.00				<u>3</u>			DAS 07 9-89 16/11/08
120 *120* Thermoform Thermoforming Machine	THERMOFORMING MACHINE Memo Thermoform as per Dwg. D3690-1and Folio FTA 019 Dwg. Rev. <u>C</u> Folio Rev. <u>D</u> Visually inspect for proper formation of each part	0.00 0.10				<u>2</u>	<u>1</u>		DAS 07 9-89 16/11/08 PTO →

DQA:

Date: 2017-02-16



QA Closed:

Date: FEB - 6 2017

WORK ORDER NON-CONFORMANCE / UPDATE

Work Order update only ☐

Work Order: <u>151454</u> Part No. <u>D3690</u> NCR No. <u>17-6258</u>	DISPOSITION Rework ☐ Scrap ☒ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☒ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date: <u>16/11/08</u>	Step #: <u>120</u>	QTY Effective: <u>1</u>		MRB (QS1042) Approval DAS <u>9</u> 9-89 <u>16-11-16</u>	
Description Work Order Deviation ONE part did not form properly.		Disposition ADJUST PLATEN LEVEL SCRAP AND REPLACE 1 PART.		Completed By DAS 16/11/08	
				Lead hand / Supervisor Approval Verification DAS <u>9</u> 9-89 <u>16-11-16</u>	
				QC / QA Coordinator Approval DAS <u>9</u> 9-89 <u>16-11-16</u>	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☒ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mis-labeled ☐ Fit/Function ☒ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : ☐			

Work Order ID 151454

Tuesday, September 27, 2016 11:53:51 AM

151454

Page 3

Item ID: D3690-1

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Glareshield

Start Date: 9/21/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 9/27/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

NR1

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150 *150* Thermoform Thermoforming Machine	HAND FINISHING THERMOFORMING Memo Trim to Finished Dimensions as per dwg D3690 using DT9036 / DT9043 template	0.00 0.28				<u>2</u>			DAS 07 9-89 10/11/08
160 *160* QC Quality Control	QC2- Inspect parts off machine FAI/FAIB Memo Check dimensions to ensure conformity to drawing tolerances.	0.00 0.00				<u>2</u>			DAS 07 9-89 10/11/08
170 *170* QC Quality Control	QC5- Inspect part completeness to step on W/O Memo	0.00 0.00				<u>2</u>			DAS 38 9-89 NOV 10 2016

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Work Order ID 151454

Tuesday, September 27, 2016 11:53:51 AM

151454

Page 4

Item ID: D3690-1

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Glareshield

Start Date: 9/21/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 9/27/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

180

Identify as per dwg & Stock Location: 5637 A

0.00

180

Packaging

Memo

0.00

Packaging

2

NOV 14 2016

DAS
9-29

190

QC21 - Final Inspection - Work Order Release

0.00

190

QC

Memo

0.02

Quality Control

DAS
21
9-29

NOV 15 2016

DAS
21
9-29

NOV 14 2016

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Tuesday, September 27, 2016 11:53:51 AM

Page 1

Work Order ID: 151454

151454

Parent Item: D3690-1

D3690-1

Parent Item Name: Glareshield

Start Date: 9/21/2016

Required Date: 9/27/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev A New Issue 08/04/28 DL verified by:DD
IPP Rev:B 08-07-14 revB as per dwg DD verified by:ec
IPP Rev:C 08-10-07 revC as per dwg DD verified by:EC Ipp Rev. D
Add Step 115 Dry Material 10/04/21 DL

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MLEXS.093-F6006-02		Purchased			No		sf	802.7434		26.32316			DAS 07 9-89
MI FXS 093-F6006-02									**				
GE PLASTICS LEXAN SHEET (BLACK)													ke/u/08

Location

Loc Qty

Loc Code

therm

802.74337

802.74337

m127208

78.97 sq ft.

DQA: _____ Date: _____


WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. ~~151454~~ 151454 MJS
1609-28

RELEASED
28-09-14

PART LIST

QTY -041	PART NUMBER	DESCRIPTION
X	D3690-041	GLARESHIELD ASSEMBLY
1	D3690-1	GLARESHIELD
1	D3697-041	TUBE ASSEMBLY
1	D3698-1	SUPPORT ANGLE
2	AN960JD3	WASHER (OR NAS1149DN332J)
2	MS20426AD3-5	RIVET
35	CR3213-4-03	RIVET

D3690-041 GLARESHIELD ASSEMBLY

C	SHEET 1 PL MS20426AD3-5 RIVET WAS MS20426AD3-4, CR3213-4-03 RIVET WAS MS20470AD3-4, WASHER QTY WAS 6 (VIEWS UPDATED ACCORDINGLY). RIVETS ON SHEET 1 CHANGED TO REF QTY. RIVETS ON SHEET 2 CHANGED TO "HARD" CALLOUTS. SHADING REMOVED FROM ALL VIEWS FOR CLARITY.	AJS	08.09.02
B	ADD FINISH COAT & 1.0 TYP. SHEET 2 ZONES A, B & C, 5. ADD MIN THICKNESS. SHEET 3 ZONE A, B	RF	08.06.24
A	NEW ISSUE	RF	08.05.26
REV.	DESCRIPTION	BY	DATE
DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF	DRAWING NO.	REV. C
CHECKED		D3690	SHEET 1 OF 3
MFG. APPR.		TITLE	SCALE
APPROVED		GLARESHIELD ASSEMBLY	NTS
DE APPR.		COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	
DATE	08.09.02		

TRANSFER DRILL $\phi 0.128$
FROM D3698-1 TO D3690-1
INSTALL
CR3213-4-03 RIVET, 20 PL
RIVET HEAD ON GLARESHIELD
OUTSIDE SURFACE



D3690-1
GLARESHIELD
REF

TRANSFER DRILL $\phi 0.098$
FROM D3697-041 TO D3690-1
INSTALL
MS20426AD3-5 RIVET
AN960JD3 WASHER (ON GLARESHIELD
OUTSIDE SURFACE)
1 PER SIDE

TRANSFER DRILL $\phi 0.128$
FROM D3697-041 TO D3690-1
INSTALL
CR3213-4-03 RIVET 2
BOTH ENDS

0.14
REF

SECTION A-A




D3690-041 GLARESHIELD ASSEMBLY

NOTES:

- 1) CENTER D3697-041 AND D3698-1 ON TO D3690-1
- 2) FINISH: PAINT D3690-041 ASSY FLAT BLACK USING BASF GLASURIT 22 LINE CODE SFA39 50 PER DART QSI 005 4.2
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) IDENTIFICATION: ETCH WITH DART P/N D3690-041 & B/N ON INSIDE OF PART
- 5) WEIGHT: 2.98 lbs
- 6) MASK HATCHED AREAS (6 PLS) ON INSIDE OF THE PART PRIOR TO PAINTING

RELEASED
08-09-14

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. C
MFG. APPR.		D3690	SHEET 2 OF 3
APPROVED		TITLE	SCALE
DE APPR.		GLARESHIELD ASSEMBLY	NTS
DATE	08.09.02	COPYRIGHT © 2008 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			



D3690-1 GLARESHIELD


NOTES:

- 1) MATERIAL: F6006 SUEDE/POLISHED 701 BLACK FLAT LEXAN SHEET 0.093 THICK
(REF DART SPEC MLEXS.093-F6006-02)
- 2) TOOLING: THERMOFORM PER MOLD DT9010 PER QSI 022
TRIM PER MOLD SCRIBE LINES EXCEPT WHERE NOTED
- 3) FINISH: NONE
- 4) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) UNITS: INCHES UNLESS OTHERWISE NOTED
- 6) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 7) IDENTIFICATION: NONE
- 8) WEIGHT: 2.5 lbs
- 9) MINIMUM THICKNESS AFTER FORMING IS 0.040

RELEASED
07-07-11

DETAIL B

SCALE 2X
THIS VIEW FOR REFERENCE ONLY



DESIGN	RF	DART AEROSPACE LTD	
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. C
MFG. APPR.		D3690	SHEET 3 OF 3
APPROVED		TITLE	SCALE
DE APPR.		GLARESHIELD ASSEMBLY	NTS
DATE	08.09.02	COPYRIGHT © 2008 BY DART AEROSPACE LTD	
THIS DOCUMENT IS CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD			